

TWISS LABORATORIES

26276 Twelve Trees Lane, Suite C Poulsbo, WA 98370 Telephone (360) 779-5141 FAX (360) 779-5150

IOC - LCR

IOC - LCR by EPA Methods 200.9, 200.7

Distribution System - Report of Analysis

IOC - LCR	Group: A
System ID No: IH3826	System Name: 7 Cedars Casino
DOH Source No:	County: Clallam
Sample Purpose: I	Date Received: 6/3/2015
	Date Analyzed: 6/5/2015
	Date Reported: 6/11/2015
Send Report To: Jamestown S'Klallam Tribe 1033 Old Blyn Hwy Sequim, WA 98382	Bill To: Jamestown S'Klallam Tribe 1033 Old Blyn Hwy Sequim, WA 98382

DOH #	Lead, mg/L	Copper, mg/L
SRL, mg/L	0.001	0.02
Trigger Level, mg/L	--	--
MCL, mg/L	*	*
Analytical Method (Analyst Init.)	EPA 200.9 KW	EPA 200.7 KW <i>MP</i>

Sample #	Date Collected	Sample Location	Lead, mg/L	Copper, mg/L
01086001	6/3/2015	CA-03	0.002	4.06
01086002	6/3/2015	CA-04	0.001	5.09
01086003	6/3/2015	CA-05	0.002	3.83
01086004	6/3/2015	CA-14	<0.001	5.08
01086005	6/3/2015	CA-17	0.005	6.61
01086006	6/3/2015	CA-19	0.004	4.61
01086007	6/3/2015	CA-23	<0.001	8.36
01086008	6/3/2015	CA-26	<0.001	4.13
01086009	6/3/2015	CA-27	0.001	6.98
01086010	6/3/2015	CA-28	<0.001	4.78

TWISS LABORATORIES

26276 Twelve Trees Lane, Suite C Poulsbo, WA 98370 Telephone (360) 779-5141 FAX (360) 779-5150

IOC - LCR

IOC - LCR by EPA Methods 200.9, 200.7

Distribution System - Report of Analysis

IOC - LCR	Group: A
System ID No: IH3826	System Name: 7 Cedars Casino
DOH Source No:	County: Clallam
Sample Purpose: I	Date Received: 6/3/2015
	Date Analyzed: 6/5/2015
	Date Reported: 6/11/2015
Send Report To: Jamestown S'Klallam Tribe 1033 Old Blyn Hwy Sequim, WA 98382	Bill To: Jamestown S'Klallam Tribe 1033 Old Blyn Hwy Sequim, WA 98382

DOH #	Lead, mg/L	Copper, mg/L
SRL, mg/L	0.001	0.02
Trigger Level, mg/L	--	--
MCL, mg/L	*	*
Analytical Method (Analyst Init.)	EPA 200.9 KW	EPA 200.7 KW

Sample #	Date Collected	Sample Location	Lead, mg/L	Copper, mg/L
----------	----------------	-----------------	------------	--------------

* Lead has not been assigned an MCL, it has an 'Action Level' of 0.015 mg/L designated by EPA. Copper has not been assigned an MCL, it has an 'Action Level' of 1.3 mg/L designated by EPA.

SRL: (State Reporting Level), indicates the minimum reporting level required by the Washington Department of Health (DOH).

Trigger Level: DOH Drinking Water response level. Systems with compounds detected at concentrations in excess of this level are required to take additional samples. Contact your regional DOH office for further information.

MCL: (Maximum Contaminant Level), If the contaminant amount exceeds the MCL, immediately contact your regional DOH office.

NA: (Not Analyzed), in the results column indicates this compound was not included in the current analysis.

ND: (Not Detected), in the results column indicates this compound was analyzed and not detected at a level greater than or equal to the SRL

< (0.00x): indicates the compound was not detected in the sample at or above the concentration indicated.

TWISS LABORATORIES

26276 Twelve Trees Lane, Suite C Poulsbo, WA 98370 Telephone (360) 779-5141 FAX (360) 779-5150

IOC - SHORT

IOC - SHORT by Various EPA Approved Methods

Source / Point of Entry - Report of Analysis

<p>Date Collected: 6/3/2015</p> <p>System ID No: IH3826</p> <p>Lab - Sample #: 01085901</p> <p>Sample Location: CA-03</p> <p>Sample Purpose: I</p> <p>Sample Composition: S</p> <p>Send Report To: Jamestown S'Klallam Tribe 1033 Old Blyn Hwy Sequim, WA 98382</p>	<p>Group: A</p> <p>System Name: 7 Cedars Casino</p> <p>County: Clallam</p> <p>DOH Source No:</p> <p>Date Received: 6/3/2015</p> <p>Date Analyzed: 6/3/2015</p> <p>Date Reported: 6/10/2015</p> <p>Sample Type: Post-treatment/Finished</p> <p>Collected By: Ian Jones</p> <p>Phone Number: 360-477-8673</p> <p>Bill To: Jamestown S'Klallam Tribe 1033 Old Blyn Hwy Sequim, WA 98382</p>
---	--

DOH#	Analyte	Results	Units	SRL	Trigger	MCL*	MCL Exceeded	Method (Analyst Init.)
16	Conductivity	313	µS/cm	70		700		SM 2510 B (DT)
405	Calcium	27.8	mg/L	0.05				EPA 200.7 (KW)
403	Alkalinity	146	µg/L as CaCO ₃	3				SM 2320 B (KW)

SRL: (State Reporting Level), indicates the minimum reporting level required by the Washington Department of Health (DOH).

Trigger Level: DOH Drinking Water response level. Systems with compounds detected at concentrations in excess of this level are required to take additional samples. Contact your regional DOH office for further information.

MCL: (Maximum Contaminant Level), If the contaminant amount exceeds the MCL, immediately contact your regional DOH office.

NA: (Not Analyzed), in the results column indicates this compound was not included in the current analysis.

ND: (Not Detected), in the results column indicates this compound was analyzed and not detected at a level greater than or equal to the SRL

< (0.00x): indicates the compound was not detected in the sample at or above the concentration indicated.

* The 0.010 mg/L MCL for Arsenic is for Group A NTNC systems. All other systems should check with their county Health District to determine what level is applicable.

TWISS LABORATORIES

26276 Twelve Trees Lane, Suite C Poulsbo, WA 98370 Telephone (360) 779-5141 FAX (360) 779-5150

IOC - SHORT

IOC - SHORT by Various EPA Approved Methods

Source / Point of Entry - Report of Analysis

<p>Date Collected: 6/3/2015</p> <p>System ID No: IH3826</p> <p>Lab - Sample #: 01088301</p> <p>Sample Location: CA-2E</p> <p>Sample Purpose: I</p> <p>Sample Composition: S</p> <p>Send Report To: Jamestown S'Klallam Tribe 1033 Old Blyn Hwy Sequim, WA 98382</p>	<p>Group: A</p> <p>System Name: 7 Cedars Casino</p> <p>County: Clallam</p> <p>DOH Source No:</p> <p>Date Received: 6/3/2015</p> <p>Date Analyzed: 6/5/2015</p> <p>Date Reported: 6/11/2015</p> <p>Sample Type: Post-treatment/Finished</p> <p>Collected By: Ian Jones</p> <p>Phone Number: 360-477-8673</p> <p>Bill To: Jamestown S'Klallam Tribe 1033 Old Blyn Hwy Sequim, WA 98382</p>
---	--

DOH#	Analyte	Results	Units	SRL	Trigger	MCL*	MCL Exceeded	Method (Analyst Init.)
405	Calcium	27.4	mg/L	0.05				EPA 200.7 (KW)
16	Conductivity	308	µS/cm	70		700		SM 2510 B (KW)
403	Alkalinity	155	µg/L as CaCO ₃	3				SM 2320 B (KW)

SRL: (State Reporting Level), indicates the minimum reporting level required by the Washington Department of Health (DOH).

Trigger Level: DOH Drinking Water response level. Systems with compounds detected at concentrations in excess of this level are required to take additional samples. Contact your regional DOH office for further information.

MCL: (Maximum Contaminant Level), If the contaminant amount exceeds the MCL, immediately contact your regional DOH office.

NA: (Not Analyzed), in the results column indicates this compound was not included in the current analysis.

ND: (Not Detected), in the results column indicates this compound was analyzed and not detected at a level greater than or equal to the SRL

< (0.00x): indicates the compound was not detected in the sample at or above the concentration indicated.

* The 0.010 mg/L MCL for Arsenic is for Group A NTNC systems. All other systems should check with their county Health District to determine what level is applicable.